



中国民用航空局
CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

维修许可证

MAINTENANCE ORGANIZATION CERTIFICATE

编号/No. F00100117

单位名称/NAME OF ORGANIZATION:

Timken Aerospace Bearing Repair

单位地址/BUSINESS ADDRESS:

4422 Corporate Center Drive Los Alamitos California 90720 USA

经审查，该单位符合中国民用航空规章第 145 部的要求，可以从事如下类别的维修工作：

Upon finding that the organization complies with the requirements of **CHINA CIVIL AVIATION REGULATION(CCAR)** Part 145, the above organization is adequate to accomplish maintenance of the following ratings:

Component Maintenance

- ☆ -

本许可证除被放弃、暂停或吊销，在下述期限内将一直有效。

This certificate, unless cancelled, suspended, or revoked, shall continue in effect until:

2021-12-31

局长授权/FOR THE ADMINISTRATOR OF CAAC

签字/SIGNATURE:

XUE Shijun

职务/POSITION:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

1999-09-03

再次颁发日期/DATE REISSUED:

2019-11-03





中国民用航空局
CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

许可维修项目

LIMITATION OF MAINTENANCE ITEMS

限定/LIMITATION:

对第 FO0100117 号许可证所列维修类别限定如下地点和项目:

Location and items set forth on Maintenance Organization Certificate No. FO0100117
is/are limited to the following:

LOCATION: Los Alamitos California

Inspection, Repair, Overhaul and Modification of the following Components:

Electrical Power (ATA-24): Limit to Alternator-Generator Drive.

Airborne Auxiliary Power (ATA-49): Limit to APU Core Engine.

Turbine/turboprop Engine (ATA-72): Limit to Engine (Turbine/Turboprop); Turbine Engine Compressor Section; Turbine Engine Combustion Section; Turbine Section; Turbine Engine Accessory Drive; Turbine Engine Oil System.

Starting (ATA-80): Limit to Engine Starter.

Detail as listed in CAAC approved maintenance capability list.

- ☆ -

局长授权/ FOR THE ADMINISTRATOR OF CAAC

签字/SIGNATURE:

XUE Shijun

职务/POSITION:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

1999-09-03

再次颁发日期/DATE REISSUED:

2019-11-05

