

Failure to observe the following warnings could create a risk of death or serious injury.

Static electricity created by a belt in operation can ignite an explosive atmosphere. Special care must be taken in the utilization of belts in or near locations which may contain explosive concentrations of combustible gases or accumulations of dust such as grain, coal, or other combustible materials.

Proper dissipation of such potential static electricity discharge must be assured to prevent any such explosion.



Failure to observe the following cautions could create a risk of serious physical injury or property damage.

Proper selection and installation of drive belts are critical tasks.

Belts must be properly selected and fitted to assure proper
performance. Always follow equipment manufacturer installation
and fitting directions and selection guides.