

中国民用航空局  
CIVIL AVIATION ADMINISTRATION OF CHINA

维修许可证  
MAINTENANCE ORGANIZATION CERTIFICATE

编号/No. F00100117

单位名称

Name of the organization Timken Aerospace Bearing Repair

单位地址

Location of business 4422 Corporate Center Drive Los Alamitos California 90720  
USA

经审查，该单位符合中国民用航空规章—145 部的要求，可以从事如下类别的维修工作：

Upon finding that the organization complies with the requirements of Civil Aviation Regulation – Part 145, the above organization is adequate to accomplish maintenance of the following ratings:

Los Alamitos California

1.Component

本许可证除被放弃，暂停或吊销，在下述期限内将一直有效。

This certificate, unless cancelled, suspended, or revoked, shall continue in effect until.


2019-12-31

局长授权

For the Minister of CAAC

签字

Signature HU Zhenjiang



初次颁发日期

Date issued

1999-09-03

职务

Position Director General of FSD

再次颁发日期

Date reissued

2017-11-09

中国民用航空局  
CIVIL AVIATION ADMINISTRATION OF CHINA

许可维修项目  
LIMITATION OF MAINTENANCE ITEMS

限定:

Limitation:

对第 F00100117 号许可证所列维修类别或维修项目作如下限定:

Maintenance items set forth on Maintenance Organization Certificate

No. F00100117 is/are limited to the following:

Limited Rating:

1. Los Alamitos California

Component:

49-AIRBORNE AUXILIARY POWER, 72-ENGINE(Internal)

Detail as listed in CAAC approved maintenance capability list.

This approval will be in effect only on condition of local authority approval kept in valid.


All work should be accomplished in accordance with current manufacturer's manual and/or CAAC approved data.

局长授权

For the Minister of CAAC

签字

Signature HU Zhenjiang



初次颁发日期

Date issued

1999-09-03

职务

Position Director General of FSD

再次颁发日期

Date reissued

2017-11-09